

## Fish Passage Evaluation Field Log

Stream: Basin Cr @ 519 road

Road # 519

Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 16.184 Long 119° 10.361

Date: 7/07/17

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | **potentially**  
**Impassable** | adults only | juveniles | meets criteria

Culvert width: 1.0 ft Length: 32.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 0.0 ft

Length of jump Pool: 0.0 ft

Depth of downstream controlling riffle: 0.2 ft

Debris blocking jump pool: **yes** | no

Active channel width: 2.8 ft

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**

**Comment: Culvert is severely undersized but was installed with no slope and is now passable. But debris could easily plug the inlet making it a passage barrier.**