

Fish Passage Evaluation Data Sheet

Stream: Deer Cr Falls 3.5 mi above mouth

Road # adjacent to 24 rd Passage ID: _____

Coordinates: Lat 44° 11.737 Long 119° 28.372

Date: July 21, 2016 Crew: Neal

General

Type: Culvert | Irrigation | Other Dam | **Natural**

Rating: RED | **GREY** | GREEN

Fish bearing: No | below only | **above** | potentially

Impassable| **adults only**| juveniles| meets criteria

Jump height to Pool: 3.26 ft,

Depth of pool: 1.42 ft

Length of pool: 15.5 ft

Debris blocking jump pool: yes | **no**

Stream Substrate size: 4 to 12 ft Boulders

Potential for debris blockage: **Yes** | No

Stream Slope through the entire reach:

rise 27.34 ft / run 195.2 ft =14.0 %

Bankfull Width/Active Channel Width

Bankfull Width above Falls: 14 ft


Road Width: n/a


Wildlife

Beaver Presence: Yes | **No**

Beaver Created Obstruction: Yes | **No**

Sketch

North 



No Utilities present



Falls on Deer Cr that is a juvenile barrier only