

Fish Passage Evaluation Field Log

Stream: Deer Cr @ 089 Rd

Road # 089 Passage ID: _____

Coordinates:

Lat 44° 12.166 Long 119° 21.895

Date: July 14, 2016

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | above | potentially

Impassable| adults only| juveniles| **meets criteria**

This culvert has been removed

This culvert meets all standards of fish passage criteria so no additional measurements were taken.