

## Fish Passage Evaluation Field Log

Stream: Nfk Deer Cr at 24 rd

Road # 24 Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 11.225 Long 119° 19.692

Date: July 14, 2016

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially

Impassable| adults only| juveniles| **meets criteria**

Jump height to Pool: 0.0 ft,

**Culvert is countersunk 0.5 ft with a flat slope and stream substrate all the way through.**

Debris blocking jump pool: yes | **no**

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**