

## Fish Passage Evaluation Field Log

Stream: Buck Cr upper culvert

Road # 351 Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 10.872 Long 119° 25.055

Date: June 20, 2016

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: **No** | below only | above | potentially

Impassable| adults only| juveniles| **meets criteria**

Jump height to Pool: 0.0 ft,

**Culvert is countersunk 0.15 ft with a gravel bottom for the entire length.**

Debris blocking jump pool: yes | **no**

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**