

Fish Passage Evaluation Field Log

Stream: Vester Cr at 361 Rd

Road # 361 Passage ID: _____

Coordinates:

Lat 44° 10.886 Long 119° 23.187

Date: July 19, 2016

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially

Impassable| adults only| juveniles| **meets criteria**

Jump height to Pool: 0.0 ft,

Culvert is countersunk 0.25 ft and installed level

Depth of downstream controlling riffle: 0.1 ft

Debris blocking jump pool: yes | **no**

This culvert meets all standards of fish passage criteria so no additional measurements were taken.