Fish Passage Evaluation Field Log
Stream:Corral Cr. upper
Road #_ <u>450</u> _ Passage ID:
Coordinates:
Lat_ <u>44°09.850</u> Long_ <u>119°21.587</u>
Date: <u>July 7, 2016</u>
Crew: <u>Neal</u>
General
Type: Culvert Irrigation Other Dam Natural
Rating: RED GREY GREEN
Fish bearing: No below only above potentially
Impassable adults only juveniles meets criteria
Jump height to Pool: <u>0.1</u> ft,
2nd jump: <u>n/a</u> ft, 3rd jump: <u>n/a</u> ft
Depth of jump Pool: $\underline{0.1}$ ft filled with boulders
Length of jump Pool: <u>3.5</u> ft
Depth of downstream controlling riffle:0.1 ft

This culvert meets all standards of fish passage criteria so no additional measurements were taken.

Debris blocking jump pool: yes | no