

Fish Passage Evaluation Field Log

Stream: Corral Cr. lower

Road # 450 Passage ID: _____

Coordinates:

Lat 44°12.029 Long 119°21.374

Date: July 12, 2016

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially
Impassable| adults only| juveniles| **meets criteria**

Jump height to Pool: 0.0 ft,

2nd jump: n/a ft, 3rd jump: n/a ft

Depth of jump Pool: 0.33 ft

Length of jump Pool: 12.0 ft

Depth of downstream controlling riffle: 0.1 ft

Debris blocking jump pool: yes | **no**

This culvert meets all standards of fish passage criteria so no additional measurements were taken.