

Fish Passage Evaluation Field Log

Stream: Thorn Cr culvert #1

Road # 2170 Passage ID: _____

Coordinates:

Lat 44° 17.166 Long 119°21.709

Date: 6/12/17

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially
Impassable| adults only| juveniles| **meets criteria**

Culvert length: 27.0 ft Culvert width: 3.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 0.9 ft

Length of jump Pool: 6.6 ft

Depth of downstream controlling riffle: 0.2 ft

Debris blocking jump pool: yes | **no**

Active channel width: 4.2 ft

This culvert meets all standards of fish passage criteria so no additional measurements were taken.



Thorn Cr culvert #1 has no perch and a good jump pool