

Fish Passage Evaluation Field Log

Stream: Murderers Cr @2180 road

Road # 2180 Passage ID: _____

Coordinates:

Lat 44° 15.552 Long 119°16.144

Date: 6/7/2017

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially

Impassable| adults only| juveniles| **meets criteria**

Culvert Width: 6.0 ft Height: 3.0 ft Length: 20.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 3.0 ft

Length of jump Pool: 27 ft

Depth of downstream controlling riffle: 0.2 ft **Log sill**
providing grade control

Debris blocking jump pool: yes | **no**

Active channel width: 10.4 ft

This culvert meets all standards of fish passage criteria so no additional measurements were taken.

Sorry no photo available