

## Fish Passage Evaluation Field Log

Stream: Murderers Cr @ USFS 233 road

Road # USFS 233 Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 15.874 Long 119° 12.833

Date: 7/18/17

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially  
Impassable| adults only| juveniles| **meets criteria**

**Small Beaver dam at inlet could worsen.**

Culvert width: 5.5 ft Length: 32.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 1.2 ft

Length of jump Pool: 13.5 ft

Depth of downstream controlling riffle: 0.2ft

Debris blocking jump pool: yes | **no**

Active channel width: 13.0 ft

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**



*Culvert inlet with old beaver dam across it that could get worse*