

## Fish Passage Evaluation Field Log

Stream: Murderers Cr @ 137 rd

Road # 137

Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 15.534

Long 119° 11.977

Date: 7/07/17

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially  
Impassable| adults only| juveniles| **meets criteria**

Culvert width: 5.7 ft      Length: 30.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 0.0 ft (No jump pool needed)

Length of jump Pool: 0.0 ft

Depth of downstream controlling riffle: 0.3 ft

Debris blocking jump pool: yes | **no**

Active channel width: 6.7 ft

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**

Comment: **Culvert is a little undersized but was installed with zero slope and has substrate its entire length.**



*Culvert outlet showing no perch and stream bed material through its entire length*