

## Fish Passage Evaluation Field Log

Stream: Sfk Murderers Cr @ USFS 2490 road

Road # USFS 2490 Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 15.744 Long 119° 22.198

Date: 8/22/17

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially  
Impassable| adults only| juveniles| **meets criteria**

Culvert width: 6.0 ft Length: 30.5 ft

Jump height to Pool: 0.5 ft

Depth of jump Pool: 1.8 ft

Length of jump Pool: 32.0 ft

Depth of downstream controlling riffle: 0.2 ft

Debris blocking jump pool: yes | **no, but trees are  
closing in.**

Active channel width: 6.4 ft

**This culvert meets all standards of fish passage  
criteria so no additional measurements were  
taken.**



*Culvert outlet showing flat slope with minimal jump height and deep jump pool*