

## Fish Passage Evaluation Field Log

Stream: Orange Cr Culvert @ 233 road

Road # USFS 233 Passage ID: \_\_\_\_\_

Coordinates:

Lat 44° 15.542 Long 119° 15.777

Date: 7/06/17

Crew: Neal

### General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially  
Impassable| adults only| juveniles| **meets criteria**

Culvert width: 2.0 ft Length: 30.0 ft

Jump height to Pool: 0.0 ft

Depth of jump Pool: 0.0 ft

Length of jump Pool: 0.0 ft

Depth of downstream controlling riffle: 0.0ft

Debris blocking jump pool: yes | **no**

Active channel width: 3.2 ft

Culvert has stream bed material through its entire length.

**This culvert meets all standards of fish passage criteria so no additional measurements were taken.**

Sorry no Photo available for this culvert