

Fish Passage Evaluation Field Log

Stream: Deer Cr Falls at RM 0.3

Road # n/a

Passage ID: _____

Coordinates:

Lat 44° 11.594 Long 119° 31.254

Date: July 21, 2016

Crew: Neal

General

Type: Culvert | Irrigation | Other Dam | **Natural**

Rating: RED | **GREY** | GREEN

Fish bearing: No | below only | **above** | potentially
Impassable| **adults only**| juveniles| meets criteria

Greatest Jump height to Pool: 5.02 ft,

2nd highest jump: 4.15 ft, 3 rd jump: 2.51 ft

All jumps pools were over 1.5 ft deep

All jumps pools were over 4.0 ft long

Debris blocking jump pool: yes | **no**

Stream Substrate size: 4 to 12 ft Boulders

Potential for debris blockage: **Yes** | No

Stream Slope through the entire reach:

rise 27.34 ft, run 195.2 ft = 14.0 %

Bankfull Width/Active Channel Width

Bankfull Width above Falls: 14 ft


Road Width: n/a ft

Wildlife

Beaver Presence: Yes | **No**

Beaver Created Obstruction: Yes | **No**

Sketch





Deer Creek lower Falls during high water



Upper most barrier (4th barrier)