

Fish Passage Evaluation Field Log

Stream: Nfk Deer at 514 rd

Road # 514 Passage ID: _____

Coordinates:

Lat 44° 11.441 Long 119° 19.126

Date: July 14, 2016

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially

Impassable| adults only| juveniles| **meets criteria**

**3 ft dia culvert that is countersunk 1.5 ft at inlet
and 2.5 ft at outlet. PASSABLE**

Debris blocking jump pool: yes | **no**

**This culvert meets all standards of fish passage
criteria so no additional measurements were
taken.**