

Fish Passage Evaluation Field Log

Stream: Blue Cr lower culvert

Road # 24 Passage ID: _____

Coordinates:

Lat 44° 12.402 Long 119° 22.851

Date: July 14, 2016

Crew: Neal

General

Type: **Culvert** | Irrigation | Other Dam | Natural

Rating: RED | GREY | **GREEN**

Fish bearing: No | below only | **above** | potentially
Impassable| adults only| juveniles| **meets criteria**

Jump height to Pool: - 0.6 ft,

Depth of jump Pool: 0.0 ft

Length of jump Pool: 0.0 ft

Depth of downstream controlling riffle: 0.1 ft

Debris blocking jump pool: yes | **no**

Culvert is countersunk 0.6 ft at outlet with cobble and gravel inside the entire length.

This culvert meets all standards of fish passage criteria so no additional measurements were taken.